	SONARtrac™ Technical Bulletin	
	Subject: Transmitter Clock	TB007 Rev: 01
		Priority: 3
Page 1 of 2		

Problem:

On all transmitters programmed with Firmware Release 03.00.14 and later firmware versions, erroneous date and time stamps can be stored in the transmitter internal data log file resulting in incorrect date and time stamps when downloading a Data History or Snapshot file.

Resolution:

Always select '→**CLEAR HISTORY**' under the transmitter '**DIAGNOSTICS**' menu whenever the date or time is changed in the transmitter.

Note: It is recommended that a Data History file is downloaded (using transmitter clock as timestamp) and the correct timestamp verified following any clock change procedure. This will ensure that the transmitter is applying the proper timestamp to data in the Data History file.


This procedure will be incorporated into the next manual release.

Priority Code:			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

CiDRA Corporation
Tel. 203-265-0035

50 Barnes Park North
Fax. 203-294-4211

Wallingford, CT 06492
www.cidra.com

	SONARtrac™ Technical Bulletin	
	Subject: Transmitter Clock	TB007 Rev: 01
		Priority: 3
		Page 2 of 2

Document Change History

Date	Revision	Changed By	ECO #	Description of Change
10/30/06	01	B Markoja	E06-0087	Initial Release

Priority Code:			
1	Safety issue or system will not function	2	Intermittent problem causing system crash
3	Erratic data/readings	4	Added product feature
5	Product enhancement		

CiDRA Corporation
Tel. 203-265-0035

50 Barnes Park North
Fax. 203-294-4211

Wallingford, CT 06492
www.cidra.com